



International Carwash Association
Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

Toyota Sienna Rear Bumper

The rear bumper on the Toyota Sienna Minivan can become loose at the rear wheel opening. This is especially hazardous if it is caught by the side wraps, as the quarter panel can deform and destroy the bumper cover and separate the wraps from the body.

To resolve the issue, Toyota altered the design of the bumper cover fitting, which was the source of the problem. It was corrected for all vehicles produced on or after October 28, 2003, including the 2004 model. The changes were incorporated into production starting with the following vehicles:

2WD: VIN#STDBA23C54S004460

4WD: VIN#5TDZA23CX45041163

If the described problem should occur in your car wash on Toyota Sienna Minivan models manufactured after October 28, 2003, please alert the International Carwash Association by submitting a Damage Report.