

Chevrolet Colorado and GMC Canyon Water Leaks on Passenger Floor

The 2004-2009 Chevrolet Colorado and GMC Canyon can leak water from the HVAC (blower case door) while going through a car wash.

General Motors identified this issue on Document ID 2177558. The problem is that with the rush of water in a car wash, the cowl deflector may not be capable of diverting all of the water. If the vehicle's HVAC is left in "Fresh Air" mode, the water may enter the HVAC case and drip on the passenger floor.

To correct this condition, General Motors recommends that when the subject vehicles travel through a car wash, the HVAC "Recirculation" mode be used. "Recirculation" mode can only be used in "Bi-Level" and "Vent" HVAC modes. This diagnostic process should correct the water leak problem.

Joe Ward