



International Carwash Association
Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

General Motors 2007 Full Size SUV Door Belt Molding

The rear door belt molding on the 2007 Chevrolet Tahoe and Suburban, GMC Yukon and the Cadillac Escalade has on occasion been loose, missing or falling off.

General Motors is currently working on this condition and updated parts will be available in the near future along with a bulletin describing the change.

Since the vehicles described above are under warranty, it is suggested that if the molding is missing or falls off in your car wash, have the owner of the vehicle return to their dealership for repair or replacement.

The new part replacement date and the bulletin information will be published on **www.CarCareCentral.com/VehicleAlerts** as soon as they are made available by General Motors.

If you have any questions, please contact Joe Ward at ICA Headquarters at ica@smithbucklin.com.