



International Carwash Association
Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

General Motors Bulletin for 2007 Full Size SUV Rear Window Wiper

As previously reported, the rear window wiper arm on the 2007 Cadillac Escalade and Escalade ESV, the 2007 Chevrolet Suburban and Tahoe and the 2007 GMC Yukon, Yukon XL and the Yukon Denali can be broken or become inoperative in an automatic car wash.

General Motors has responded by issuing [Bulletin No. 07-08-43-001](#) which directs the GM dealership to install an updated rear wiper arm park ramp and replace the rear wiper arm or blade if damaged.

If this damage should occur in your car wash, suggest that your customer return to their dealership for the rear wiper repair. Please note, General Motors has not committed to making any free repairs for vehicles out of warranty and has incorporated the new rear wiper correction into production starting the last week of August 2006.

Please [report any vehicle damage](#) occurring at your wash and share all [Vehicle Alerts](#) with your staff.

If you have any questions, please contact the International Carwash Association at <mailto:info@CarCareCentral.com>.